




Fabric Support Officer Levels of Support

- Places of Worship with their own surveyors/architect
- Places of worship with their regular contractor and volunteers
- Places of worship requiring other types of assistance



Archdiocese of Liverpool



Places of worship with new volunteers and regular contractors



St Paul's Church, Halliwell – Grade II



St Chad's Church, Rochdale – Grade II*

Places of worship requiring other types of assistance



All Saints, Barton, Grade I



Shaare Rachamim Synagogue, Grade II



Conclusion

- Positive response to advice and grants
- Challenge will be making sure that the POW's have Maintenance Plans which they will follow
- Clear message that they need larger grants as well as small scale maintenance funding
- Concerns that whilst Parishes may be able to afford the repair works, the cost of high level access is preventing them undertaking 'stitch in time' works such as gutter clearance.